



International
LONGSHORE & WAREHOUSE
UNION

I.L.W.U. Local 500

December 18, 2006

ATTENTION

During discharge of cargo there is to be no ship dunnage, steel bands or garbage of any kind put on top of loads leaving the hatch.

Dirt nets and/or dirt boxes are to be lowered into the hatch and garbage is to be removed in this manner.

In Solidarity
ILWU Local 500 Safety Committee