



International
**LONGSHORE & WAREHOUSE
UNION**

LOCAL 500
March 12, 2007

SAFETY BULLETIN

STAY ALERT!

Recently, at Lynnterm East Gate, some large diameter pipe was being loaded out onto trucks when the cross bracing at one end broke loose and **FLEW** approximately **40 FT.**

Upon closer examination, the welds holding the cross bracing were **NOT** up to standard. The company and the customer have been advised. Please be aware of this.

The bight can present itself in many different ways.

In solidarity
ILWU Local 500 Safety Committee